PATTISON AGRICULTURE LIMITED

P.O. Box 248 Yorkton, SK S3N 2V7 Phone: (306) 783-9459 Fax: (306) 783-7177 Http://www.pattisonag.com GST Number 818708372

Swift Current, SK Maple Creek, SK Kindersley, SK Kyle, SK Leader, SK Unity, SK North Battleford, SK Humboldt, SK Kelvington, SK Shaunavon, SK

(306) 773-9351 (306) 662-2233 (306) 463-2683 (306) 375-2302 (306) 628-3889 (306) 228-2696 (306) 445-4468 (306) 682-2572 (306) 327-4355 (306) 297-2639

Yorkton, SK (306) 783-9459 Balcarres, SK Moosomin, SK Preeceville, SK Russell, MB Wynyard, SK

Kamsack, SK

Serial Number:

N/A

(306) 334-2492 (306) 435-3301 (306) 547-2007 (204) 773-2149 (306) 554-2536 (306) 542-2814 Swan River, MB (204) 734-3466





Invoice To Account No: 62296

D.M. DUTCHAK FARMS LTD. DARRELL DUTCHAK

Bus Phone: (306)593-7774

BOX 1521

Yorkton SK S3N 3K3

BOX 1521 SW 05 32 07 W2 Yorkton SK S3N 3K3

> Bus Phone: (306)593-7774

Deliver To:

Meter

D.M. DUTCHAK FARMS LTD.

Prv Phone:

Invoice Number: Invoice Date

Location: Work Order Number: Payment Type: Authorization Number:

EQ Id:

DD3010

Page:

3340206

SERVICE INVOICE

Fleet No:

03/25/2025 11 483611

Credit Card V027233

1 of 2

Make/Model:

Prv Phone:

JOHN DEERE 3010

Service Reminders:

JGEN01- Retail

COMPLAINT:

CHANGE BATTERIES

CORRECTION:

Replaced batteries

PartNumber TY24341B TY24341B-CR

Description Wet Charged Battery CORE for:Wet Charged Battery

Parts: \$608.98

OL&M: \$0.00

Quantity 2.00

-2.00

\$0.00

Misc:

Net Price 331.49 27.00

Sub-Total:

Extended Price Taxed Ind \$662.98 -\$54.00

\$808.98

Y

JGEN02- Retail

Labor: \$200.00

COMPLAINT:

TRACTOR WON'T STAY RUNNING.

CORRECTION:

Removed lines leaving lift pump - cranked engine no fuel pressure. Tried to hand prime with lines on and still no fuel. Ordered lift pump emergency from Regina

Changed lift pump - primed and started engine, ran well Took for drive it did not stall out - ran good

<u>PartNumber</u> DZ126575 X1/8HP-S

Miscellaneous

FRT

Description Fuel Pump

-2mNPT plug Hex **Description**

FREIGHT

Quantity 1.00

Quantity

1.00

1.00

Net Price Extended Price Taxed Ind 276.73 1.32

35.00

\$276.73 \$1.32 Net Price Extended Price

Taxed Ind

Miscellaneous Charges:

SERVICE ACCESSORIES

\$110.00

Labor: \$900.00

Parts: \$278.05

OL&M: \$0.00

Misc:

\$145.00

Sub-Total:

\$1,323.05

\$35.00

PATTISON AGRICULTURE LIMITED

P.O. Box 248 Yorkton, SK S3N 2V7 Phone: (306) 783-9459 Fax: (306) 783-7177 Http://www.pattisonag.com GST Number 818708372

Swift Current, SK Maple Creek, SK Kindersley, SK Kyle, SK Leader, SK Unity, SK North Battleford, SK Humboldt, SK Kelvington, SK

Shaunavon, SK

(306) 773-9351 (306) 662-2233 (306) 463-2683 (306) 375-2302 (306) 628-3889 (306) 228-2696 Wynyard, SK (306) 445-4468 Kamsack, SK (306) 682-2572 Swan River, MB (306) 327-4355

Yorkton, SK (306) 783-9459 Balcarres, SK (306) 334-2492 Moosomin, SK (306) 435-3301 Preeceville, SK Russell, MB

(306) 547-2007 (204) 773-2149 (306) 554-2536 (306) 542-2814 (204) 734-3466





Invoice To Account No: 62296

D.M. DUTCHAK FARMS LTD. DARRELL DUTCHAK

BOX 1521

Yorkton SK S3N 3K3

Bus Phone: (306)593-7774

Tyrel Frankl

Prv Phone:

Make/Model:

Deliver To:

D.M. DUTCHAK FARMS LTD. **BOX 1521**

(306) 297-2639

SW 05 32 07 W2 Yorkton SK S3N 3K3

Bus Phone: (306)593-7774

Meter

Serial Number:

N/A

Prv Phone:

SERVICE INVOICE Invoice Number: Invoice Date

Location: Work Order Number: Payment Type:

Page:

Authorization Number:

EQ ld: DD3010 Fleet No:

JOHN DEERE 3010

Service Reminders:

Customer PO No:

Tax Exempt No:

Advisor:

Credit Card Information

Type: Auth No: Amount:

Credit Card V027233 \$2,238.63

Labor: \$1,100.00 Parts:

\$887.03 OL&M: \$0.00 Misc: \$145.00 GST: \$106.60

3340206

03/25/2025

Credit Card

V027233

2 of 2

483611

11

PST: \$0.00

Grand Total: \$2,238.63

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by:	
Received by:	Date:

CTISON AGRICULTURE LIMITED

.O. Box 248 Yorkton, SK S3N 2V7 Phone: (306) 783-9459 Fax: (306) 783-7177 Http://www.pattisonag.com GST Number 818708372

Swift Current, SK Maple Creek, SK Kindersley, SK Kyle, SK

Shaunavon, SK

(306) 463-2683 (306) 375-2302 (306) 628-3889 Leader, SK (306) 228-2696 Unity, SK North Battleford, SK (306) 445-4468 Humboldt, SK (306) 682-2572 (306) 327-4355 Kelvington, SK

(306) 783-9459 Yorkton, SK (306) 334-2492 Balcarres, SK Moosomin, SK Presceville, SK Russell, MB

Wynyard, SK

Kamsack, SK

(306) 435-3301 (306) 547-2007 (204) 773-2149 (306) 554-2536 (306) 542-2814 Swan River, MB (204) 734-3466





Deliver To: Invoice To Account No: 62296

D.M. DUTCHAK FARMS LTD. DARRELL DUTCHAK **BOX 1521** Yorkton SK S3N 3K3

Bus Phone: (306)593-7774

Prv Phone:

D.M. DUTCHAK FARMS LTD. **BOX 1521**

(306) 773-9351

(306) 662-2233

(306) 297-2639

SW 05 32 07 W2 Yorkton SK S3N 3K3

(306)593-7774 Bus Phone:

Prv Phone:

Invoice Number: Invoice Date

Location: Work Order Number: Payment Type:

Authorization Number: Page:

3313252 12/30/2024

SERVICE INVOICE

11 471591 Credit Card

V061089 1 of 3

Fleet No: Serial Number: EQ Id: Meter Make/Model: DD3010 N/A JOHN DEERE 3010

Service Reminders:

JGEN01- Retail

COMPLAINT:

UNIT WON'T START

CORRECTION:

ATTEPMT TO START TRACTOR, KEY FROZEN WARM IGNITION, TURN KEY, ENGINE WOULD NOT TURN OVER ATTEMPT TO BOOST TRACTOR WITH BATTERY PACKS, WOULD NOT TURN OVER PLUG INLINE BLOCK HEATER ON TRACTOR IN LET WARM UP LEFT BATTERY PACK ON TO CHARGE BATTERIES ATTEMPT TO TURN ENGINE OVER, STILL WOULD NOT BUDGE WARM STARTER WITH PROPANE TORCH, SOLENOID STILL WOULD NOT ENGAGE WARM STARTER AND TAP WITH HAMMER, STILL WOULD NOT ENGAGE DUFFY HELPED ME TO VERIFY ELECTRICAL, BATTERYS BOTH READING 12V AND ALL ELECTRICAL APPEARED TO CHECK OUT REPLACE STARTER

	Description		Quantity	Net Price	Extended Price	Taxed Ind
<u>PartNumber</u>	Description		1.00	95,47	\$95.47	Υ
24371	GASKET KIT		1.00	228.58	\$228.58	Υ
29111	CAGE				\$5.91	Υ
B3586R	WASHER		1.00	5.91	•	
TY26673	15W40 3.78L Plus-50II CK4/SN		1.00	37.78	\$37.78	r
*	Description		Quantity	Net Price	Extended Price	Taxed Ind
Miscellaneous	ENVIRO FEE		1.00	0.60	\$0.60	<u>Y</u>
EF60		Mina	¢0.60	Sub-Total:	\$768.34	
Labor: \$400.00	Parts: \$367.74 OL&M: \$0.00	Misc:	\$0.60			

JGEN02- Retail

COMPLAINT:

RESEAL FUEL PUMP AND REPLACE WEIGHT CAGE

CORRECTION:

REMOVE RESEAL AND RE-INSTALL FUEL INJECTION PUMP tHROTTLE SHAFT SEALS LEAKING REMOVE PLATE OVER FLYWHEEL AND PUMP SIDE COVER AND BAR OVER ENGINE TO LINE UP INJECTION PUMP TIMING **MARKS** DISCONNECT THROTTLE LEVER SHUTOFF CABLE BROKEN SO DID NOT NEED TO REMOVE

TISON AGRICULTURE LIMITED Maple Creek, SK

:O. Box 248 Yorkton, SK S3N 2V7 Phone: (306) 783-9459 Fax: (306) 783-7177 Http://www.pattisonag.com GST Number 818708372

Swift Current, SK Kindersley, SK Kyle, SK Leader, SK

Unity, SK North Battleford, SK Humboldt, SK Kelvington, SK Shaunavon, SK

(306) 773-9351 Yorkton, SK (306) 783-9459 (306) 662-2233 Balcarres, SK (306) 463-2683 Moosomin, SK (306) 375-2302 Preeceville, SK (306) 628-3889 Russell, MB (306) 228-2696 Wynyard, SK

Kamsack, SK

Swan River, MB (204) 734-3466

(306) 334-2492 (306) 435-3301 (306) 547-2007 (204) 773-2149 (306) 554-2536 (306) 542-2814



Invoice To Account No: 62296 D.M. DUTCHAK FARMS LTD.

Bus Phone: (306)593-7774

DARRELL DUTCHAK

Yorkton SK S3N 3K3

D.M. DUTCHAK FARMS LTD.

(306) 445-4468

(306) 682-2572

(306) 327-4355

(306) 297-2639

BOX 1521 SW 05 32 07 W2

Yorkton SK S3N 3K3

Bus Phone: (306)593-7774

Prv Phone:

SERVICE INVOICE 3313252 Invoice Number:

12/30/2024 Invoice Date Location: 11 471591 Work Order Number: Payment Type: Credit Card Authorization Number: V061089

2 of 3

Make/Model:

BOX 1521

Prv Phone:

Meter

Serial Number:

N/A

EQ Id: DD3010 Fleet No:

JOHN DEERE 3010 Service Reminders:

DISCONNECT OVERFLOW RETURN LINE

REMOVE FUEL INLET LINE FROM FUEL FILTER

REMOVE FUEL INLET FITTING

DISCONNECT FUEL INJECTOR LINES AND MOVE OUT OF WAY

REMOVE NUTS HOLDING PUMP TO ENGINE

REMOVE PUMP

DRAIN PUMP OF DIESEL

CLEAN EXTERIOR OF PUMP TO REMOVE AS MUCH EXTERNAL DIRT AND SEDIMENT AS POSSIBLE

DISSASEMBLE INJECTION PUMP

CLEAN UP PUMP

REPLACE RETURN LINE FITTING AS THREADS WERE DAMAGED

WEIGHT CARRIER RING BROKEN UP, WEIGHT CARREIR PINS DAMAGED

MARK TIMING MARK ON NEW WEIGHT CARRIER

METERING VALVE AND PUMPING PLUNGERS STICKING DUE TO VARNISH, CLEAN UP WITH FLUID FILM

REASSEMBLE INJECTION PUMPS WITH NEW SEALS FROM GASKET KIT

LINE UP TIMING MARKS ON PUMP AND INSTALL BACK ON ENGINE

LOOSELY TIGHTEN HOLD DOWN NUTS

REINSTALL LOOSELY INJECTION LINES WITH NEW WASHERS

ROTATE PUMP TO LINE TIMING MARKS BACK UP AND TIGHTEN NUTS

TIGHTEN INJECTION LINES LEAVING ONE LOOSE TO BLEED PUMP

CLEAN AND REINSTALL FUEL INLET LINE LEAVING LOOSE

INSTALL OVERFLOW RETURN LINE

INSTALL THROTTLE LINKAGE BACK TO PUMP

BLEED INLET LINE TO PUMP AND TIGHTEN

BLEED PUMP UNTIL FUEL IS COMING OUT LOOSE INJECTION LINE AND TIGHTEN LINE

LOOSEN INJECTION LINES ON 1 AND 2 CYLINDER FUEL INJECTORS AND BLEED TO INJECTORS, TIGHTEN LINES

CRANK TO FIRE UP ENGINE AND CLEAN AIR OUT OF LINES THE REST OF THE WAY

VERIFY REPAIR AND CHECK FOR LEAKS

Net Price Extended Price Taxed Ind Description Quantity **PartNumber** \$25.21 1.00 25.21 Elbow Fitting AR26670 Sub-Total: \$1,025.21 \$0.00 Parts: \$25.21 OL&M: \$0.00 Misc: Labor: \$1,000.00

4010F875854 Retail

COMPLAINT:

STARTER, R&R

CORRECTION:

DISCONNECT BATTERY REMOVE SHIELDING DISCONNECT WIRING FROM STARTER REMOVE STARTER

TISON AGRICULTURE LIMITED

.O. Box 248 Yorkton, SK S3N 2V7

Phone: (306) 783-9459 Fax: (306) 783-7177 Http://www.pattisonag.com

GST Number 818708372

Swift Current, SK Maple Creek, SK Kindersley, SK Kyle, SK Leader, SK

(306) 628-3889 Unity, SK North Battleford, SK Humboldt, SK Kelvington, SK Shaunavon, SK (306) 297-2639

(306) 662-2233

(306) 773-9351 Yorkton, SK (306) 783-9459 Balcarres, SK (306) 334-2492 (306) 435-3301 (306) 463-2683 Moosomin, SK (306) 375-2302 Preeceville, SK

(306) 547-2007 (204) 773-2149 Russell, MB (306) 228-2696 Wynyard, SK (306) 554-2536 (306) 445-4468 Kamsack, SK (306) 542-2814 (306) 682-2572 Swan River, MB (204) 734-3466 (306) 327-4355





Invoice To Account No: 62296	Deliver To:		SE	ERVICE INVOICE
D.M. DUTCHAK FARMS LTD. DARRELL DUTCHAK BOX 1521 Yorkton SK S3N 3K3 Bus Phone: (306)593-7774	D.M. DUTCHAK FARI BOX 1521 SW 05 32 07 W2 Yorkton SK S3N 3K3		Invoice Number: Invoice Date Location: Work Order Number: Payment Type:	3313252 12/30/2024 11 471591 Credit Card
Prv Phone:	Bus Phone: (306)593	3-7774	Authorization Number:	V061089 3 of 3
Make/Model:	Meter	Serial Number:	EQ ld;	Fleet No:
JOHN DEERE 3010		N/A	DD3010	
Service Reminders:				

INSTALL NEW STARTER AND REASSEMBLE IN REVERSE ORDER

PartNumber SE501445	Description STARTER-24V Serial# 233120178	Quantity 1.00	Net Price 1,015.76	Extended Price \$1,015.76	Taxed Ind Y
SE501445-CR Miscellaneous C	CORE for:Starter Motor Reman	-1.00	104.00	-\$104.00	Υ
	_				
SERVICE ACCE	ESSORIES				\$150.00

							Ψ150.00
Labor: \$300.00	Parts: \$911.76	OL&M: 5	0.00	Misc:	\$150.00	Sub-Total:	\$1,361.76
		Credit Card	Information			Labor:	\$1,700.00
Customer PO No:		Type:	Credit Card			Parts:	\$1,304.71
Tax Exempt No:		Auth No:	V061089			OL&M:	\$0.00
Advisor:	Debbie Ford	Amount:	\$3,313.08			Misc:	\$150.60
						GST:	\$157.77
						PST:	\$0.00

Grand Total: \$3,313.08

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by:

PST/TVP TOTAL

2745 99

D.M. DUTCHAK FRAMS