



5 Kelsey Bay
Yorkton, SK • S3N 4C5

Ph: (306) 782-2233

Fax: (306) 782-2315

Toll Free: 1 (877) 988-2233

www.yorktontoyota.ca



To: A

www.yorktonauctioncentre.com
306-782-5999

Year: 2015 Veh Id: 12170

Make: Toyota

Model: SIENNA SE V6 8-P

Colour: 0040 alpine white

V.I.N.#: 5TDXK3DC7FS529000

Date In: 06/29/2023

Out: 07/07/2023

Ext. War - - (mo/) - D: \$0.00

Promised Time: 00/00/0000 00:00:00 AM Call When Ready: No

www.yorktonauctioncentre.com
306-782-5999

Next Service:
In Service Date: 02/28/2015
Cases: 8

Case: 1 Multi-point Vehicle Inspection

- Tech Cause: Per customer - Tech Comments: Performed multipoint vehicle inspection. See attached inspection paper.

Quantity Description/Correction

Price Total
\$89.95 \$89.95

- Tech Cause: Per customer
- Tech Comments: Performed multipoint vehicle inspection. See attached inspection paper.
- Completed by: Prekaski, Quentin
- Shop Charges -

\$9.42 \$9.42

Misc \$9.42 Labour \$89.95 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$99.37

Case: 2 Complaint of both power sliding doors not working and also the fan will not work when you turn on the vehicle until you hit the mode button - Tech Cause: Per customer - Tech Comments: HVAC controller is faulty, power sliding doors need centre hinges and sliding cables.

Quantity Description/Correction

Retail Price Total
\$36.36 \$0.00 \$0.00

1.00 04009-02708 - HINGE ASSY, SLIDE
DO - Warranty

\$12.44 \$0.00 \$0.00

1.00 04009-02308 - MOULDING, SLIDE
RAIL - Warranty

\$26.96 \$0.00 \$0.00

1.00 04009-02208 - CABLE SUB-ASSY,
POWE - Warranty

\$12.44 \$0.00 \$0.00

1.00 04009-02408 - MOULDING, SLIDE
RAIL - Warranty

\$36.36 \$0.00 \$0.00

1.00 04009-02608 - HINGE ASSY, SLIDE
DO - Warranty

\$26.96 \$0.00 \$0.00

1.00 04009-02108 - CABLE SUB-ASSY,
POWE - Warranty

\$0.00 \$0.00

- Tech Cause: Per customer
- Tech Comments: HVAC controller is faulty, power sliding doors need centre hinges and sliding cables. - Warranty



Friendly. Reliable. It's that simple.



5 Kelsey Bay
Yorkton, SK • S3N 4C5

Ph: (306) 782-2233
Fax: (306) 782-2315
Toll Free: 1 (877) 988-2233
www.yorktontoyota.ca

- Completed by: Prekaski, Quentin

\$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt

www.yorktonauctioncentre.com
306-782-5999

3 Customer requested silver detail package be done

Quantity	Description/Correction	Price	Total
----------	------------------------	-------	-------

• 131828 - Silver Detail		\$124.95	\$124.95
--------------------------	--	----------	----------

\$0.00	Labour \$124.95	Parts \$0.00	Prepaid Parts Amt: \$0.00	Case Total:	\$124.95
--------	-----------------	--------------	---------------------------	-------------	----------

Case: 4 Remove & Replace HEADLAMP BULB High Beam, One Side
Left high beam inoperative - Tech Cause: Per quote - Tech Comments: Removed and replaced left headlamp bulb

Quantity	Description/Correction	Retail	Price	Total
1.00	90981-13046 - BULB	\$24.95	\$24.95	\$24.95
			\$42.00	\$42.00

- Tech Cause: Per quote
- Tech Comments: Removed and replaced left headlamp bulb
- Completed by: Prekaski, Quentin
- Shop Charges -

Misc	Labour	Parts	Prepaid Parts Amt:	Case Total:	\$71.35
------	--------	-------	--------------------	-------------	---------

Case: 5 Front Pads, Replace Rotors - Tech Cause: Per quote - Tech Comments: Removed and replaced front pads and rotors

Quantity	Description/Correction	Retail	Price	Total
2.00	43512-0E030 - DISC, BRAKE	\$128.36	\$128.36	\$256.73
1.00	04465-AZ219 - FR BRAKE PAD	\$86.96	\$86.96	\$86.96
1.00	04945-0E040 - SHIM KIT, BRAKE	\$57.64	\$57.64	\$57.64
1.00	04947-0E010 - FITTING KIT, BRAKE	\$38.85	\$38.85	\$38.85
			\$220.50	\$220.50

- Tech Cause: Per quote
- Tech Comments: Removed and replaced front pads and rotors
- Completed by: Prekaski, Quentin
- Shop Charges -

Misc	Labour	Parts	Prepaid Parts Amt:	Case Total:	\$683.77
------	--------	-------	--------------------	-------------	----------

Case: 6 Rear Brakes, Replace Rotors - Tech Cause: Per quote - Tech Comments: Removed and replaced rear pads and rotors

Quantity	Description/Correction	Retail	Price	Total
2.00	42431-0E020 - DISC, BRAKE	\$158.57	\$158.57	\$317.13



5 Kelsey Bay
Yorkton, SK • S3N 4C
Ph: (306) 782-2233
Fax: (306) 782-2315
Toll Free: 1 (877) 988
www.yorktontoyota.ca

www.yorktonauctioncentre.com
306-782-5999

- 1.00 04466-AZ209 - RR BRAKE PAD
- 1.00 04946-0E060 - SHIM KIT, BRAKE
- 1.00 04948-30230 - REPAIR KIT, BRAKE

- Tech Cause: Per quote
- Tech Comments: Removed and replaced rear pads and rotors
- Completed by: Prekaski, Quentin
- Shop Charges -

07/07/2023 16:10:04		
\$86.96	\$86.96	\$86.96
\$24.95	\$24.95	\$24.95
\$42.37	\$42.37	\$42.37
	\$220.50	\$220.50
	\$0.00	\$0.00
Case Total:		\$715.00

Misc	Labour	Parts	Prepaid Parts Amt:	
Case: 7 Remove & Replace AIR CLEANER ELEMENT All Applicable Models				
Engine air filter is restricted - Tech Cause: Per quote - Tech Comments: Removed and replaced engine air filter				

Quantity Description/Correction

- Tech Cause: Per quote
- Tech Comments: Removed and replaced engine air filter
- Completed by: Prekaski, Quentin

Price	Total
\$0.00	\$0.00

Misc	Labour	Parts	Prepaid Parts Amt:	Case Total:
\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Case: 8 Cabin Air Filter Replace - Tech Cause: Per quote - Tech Comments: Removed and replaced cabin air filter				

Quantity Description/Correction

- 1.00 87139-YZZ82 - ELEMENT, AIR REFINER

- Tech Cause: Per quote
- Tech Comments: Removed and replaced cabin air filter
- Completed by: Prekaski, Quentin

Retail	Price	Total
\$33.95	\$0.00	\$0.00
	\$55.95	\$55.95

Misc	Labour	Parts	Prepaid Parts Amt:	Case Total:
\$0.00	\$21.56	\$34.39	\$0.00	\$55.95
				\$0.00